

**Flood Control Project Maintenance
Levee Inspections****LMA District Cover Sheet****Spring 2011 Levee Inspection Results****Reclamation District No. 2096 Wetherbee Lake**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2011 Levee Inspection Results

Reclamation District No. 2096 Wetherbee Lake

Waterway			Bank	Unit Miles
Unit No. 01 San Joaquin River			Right	0.17

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/12/2011 - 4/12/2011			
DWR Inspector	Jim Eto			
Accompanied By	Chuck McCabe RD 2096			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Suite 200
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2096 Wetherbee Lake

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River						Right	0.17	04/12/2011 04/12/2011	Jim Eto

LMIR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.04	0.17	Earthen Levee	Encroachments	LS	PO	Fences Inspector Comments: Fence at toe of levee obstructs access.	37.773495 ° -121.298411 °	37.772722 ° -121.298436 °	3 Y
2	0.05	0.06	Earthen Levee	Vegetation	WS	A	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: 04/12/2011 Photo shows area clear of weeds.	37.773373 ° -121.298462 °	37.773262 ° -121.298396 °	2 Y
3	0.05	0.06	Earthen Levee	Vegetation	LS	C	Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: No change to vegetation since spring.	37.773373 ° -121.298462 °	37.773262 ° -121.298396 °	1
4	0.10	0.10	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: The levee is over 40' wide in this location. Damaged slope has been recompacted but rodents have persisted.	37.772920 ° -121.298461 °	37.772920 ° -121.298461 °	8 Y

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2096 Wetherbee Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	0.17	04/12/2011 04/12/2011	Jim Eto

Levee Mile Report Line	2
Start Levee Mile	0.05
End Levee Mile	0.06
Location	Water Side
Category	Earthen Levee
Item	Vegetation

04/12/2011 Photo shows area free of vegetation.

jeto_s_20110412_379.jpg



Levee Mile Report Line	2
Start Levee Mile	0.05
End Levee Mile	0.06
Location	Water Side
Category	Earthen Levee
Item	Vegetation

04/12/2011 Photo is for reference, showing area free of vegetation.

jeto_s_20110412_380.jpg



Levee Mile Report Line	4
Start Levee Mile	0.10
End Levee Mile	0.10
Location	Land Side
Category	Earthen Levee
Item	Animal Control

Levee slope was recompacted and rodents have reestablished their den at this location.

jeto_s_20110301_272.jpg



*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2011

Reclamation District No. 2096 Wetherbee Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Right	0.17	04/12/2011 04/12/2011	Jim Eto

Levee Mile Report Line	4
Start Levee Mile	0.10
End Levee Mile	0.10
Location	Land Side
Category	Earthen Levee
Item	Animal Control
04/12/2011 Photo shows active burrows in levee on water side.	
jeto_s_20110412_381.jpg	



Levee Mile Report Line	4
Start Levee Mile	0.10
End Levee Mile	0.10
Location	Land Side
Category	Earthen Levee
Item	Animal Control
04/12/2011 Photo shows several burrows in same location, on water side of levee.	
jeto_s_20110412_382.jpg	

*** Location**

LS : Landside
WS : Waterside
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected/Rated
C : Corrected
W : Watch/Monitor